

# Known Vehicle Causes of Unintended Acceleration

»» Richard Boyd  
Acting Director  
Office of Defects Investigation

# “Sudden Acceleration Incidents”

- ▶ **Definition:** “Unintended, unexpected, high-power accelerations from a stationary position or a very low initial speed accompanied by an apparent loss of braking effectiveness.” NHTSA, *“An Examination of Sudden Acceleration,” 1989 (Silver Book)*.
- ▶ **Characteristics:**
  - Engine power: sudden, large increase in engine power, at or near wide-open throttle (WOT)
  - Brakes: allegedly ineffective (brake application often cited as initiator)
  - Initial speed: over 90% start from stationary position or low-speed
  - Location: most occur in parking lots, garages, driveways, car washes
  - Operating mode: initial shift from PARK to REVERSE or DRIVE
  - Crashes: most incidents result in crashes
  - Drivers: older drivers over-represented
  - Evidence: generally no problems with throttle control or brake systems identified in post-incident vehicle inspection or subsequent vehicle service
- ▶ **Technical summary:**
  - Evidence suggested that most SAI probably involve the driver unintentionally pressing the accelerator when braking was intended
  - No mechanism for temporary, self-correcting brake failure was found to exist

# “Unintended Acceleration”: A Broader Concept

- ▶ The Silver Book’s definition of “Sudden Acceleration” did not include all types of incidents involving unwanted engine power
- ▶ More recently, “unintended acceleration” (UA) has been used as a catch-all term that is not limited to high engine power, low initiation speeds or allegations of brake ineffectiveness
- ▶ Included in UA are the rare incidents involving prolonged open throttle events
- ▶ However, data indicate that by far the most common incidents are still those involving sudden, high-power accelerations from a stationary position or very low initiation speed, as in parking lots and driveways, that also include allegations of brake ineffectiveness

# Known Vehicle Factors for UA

- ▶ Throttle control history:
  - Over 30 years of investigations & recalls (since 1970's)
  - Wide variety of vehicle causes for unwanted engine power
  - In the last 25 years:
    - 109 defect investigations, influencing 34 recalls
    - 174 recalls involving 15.6 million products
- ▶ Vehicle Causes Identified in Investigations & Recalls:
  - Stuck Throttle
    - Conditions that prevent or inhibit throttle return to idle when the driver releases the accelerator
    - Most of these conditions do NOT involve full engine power
    - Examples: pedal entrapment, cable binding, throttle icing, cruise control servo
  - Self-Actuation
    - Conditions that cause the throttle to open or result in elevated idle speed
    - Most of these conditions do NOT involve sudden, full engine power
    - Examples: cruise control computer, engine control module, accelerator pedal sensor, high idle & engine surge conditions in heavy vehicles
  - No defect conditions have been identified that:
    - Resulted in sudden WOT; and
    - Simultaneous loss of brake effectiveness

# Investigations for UA

		INFLUENCED RECALLS		
	Subject	INV.	NO.	UNITS RECALLED
Vehicle based cause	Stuck throttle	57	29	9,428,000
	Self-actuation	11	1	5,000
Vehicle features related to pedal misapplication		41	4	1,815,000
Total		109	34	11,247,000

## Observations:

- ❑ Stuck throttle:
  - Most likely to result in an influenced recall (approx 50%)
  - 85% of influenced recalls
  - 84% of products recalled
- ❑ Vehicle features related to pedal misapplication:
  - Three recalls to install brake transmission shift interlocks (BTSI)
  - One recall to ensure adequate spacing of accelerator and brake pedals

# Recalls for UA

Category	RECALLS			PRODUCTS RECALLED		
	MFR	ODI	Total	MFR	ODI	Total
Stuck throttle	118	29	147	4,043,000	9,428,000	13,471,000
Self-actuation	21	1	22	313,000	5,000	318,000
Vehicle features related to pedal misapplication	1	4	5	1,000	1,815,000	1,815,000
Total	140	34	174	4,356,000	11,247,000	15,604,000

## Observations:

- Most recalls address defects in “stuck throttle” category
  - 84% of recalls
  - 86% of products recalled
- NHTSA influenced 20% of recalls and 72% of products recalled
- Three Toyota recalls in 2009 & 2010:
  - All involved stuck throttle conditions - pedal entrapment & sticking pedals (internal friction)
  - 7,584,000 vehicles; almost half (48%) of total since 1985

# Long-Duration, High-Speed Incidents


- ▶ Rare events – require multiple conditions
  - Defect condition must result in sustained high-power at or near WOT (e.g., floor mat entrapment, which occurs after pedal-to-floor acceleration)
  - Braking capacity (braking torque vs. drive axle torque):
    - High-power engine, high initiation speed, and depleted vacuum reduce brake effectiveness
    - Drivers initially able to manage speed for 1-2 miles, but may not be able to stop
    - Brakes lose effectiveness due to over-heating  $\Rightarrow$  speed  $\uparrow\uparrow$  (some  $>100\text{mph}$ )
  - Complex PRNDL gate design – difficulty shifting to “N”
  - Push-button ignition – difficulty turning engine “OFF”
  - See San Diego County Sheriff’s Department Incident Report concerning August 2009 crash in Santee, California (Case No. 09056454)

# Pedal Entrapment



# PRNDL Gate Design

- Drivers may attempt to shift to “Neutral”
  - PRNDL gate design for Toyota Sequential Shift vehicles may not be intuitive for location of “Neutral”
  - Drivers who successfully shift to “Neutral” may misinterpret  $\uparrow$  in engine rpm and shift back to drive



# Engine Start/Stop Switch



- Switch operation:
  - ❑ Vehicle stationary: momentary press to start and stop
  - ❑ Vehicle in-motion: must press and hold for at least 3 seconds (to avoid inadvertent shut-off)
  - ❑ Different strategies used by other manufacturers
    - Different time intervals
    - Many included shut-off with multiple press (2x or 3x)
    - Some prevent engine shutoff when moving (and not in PARK)

# Countermeasures

## ▶ Brake Transmission Shift Interlock (BTSI)

- Requires brake application for shift from PARK to ensure safe shift
- Introduced in U.S. in 1987 Audi passenger cars
- Implemented in 80% of new cars sold by 1992
- In vehicles without BTSI, approximately 70% of UA incidents occurred upon shift from PARK to REVERSE or DRIVE
- Effect on UA experience:
  - When first implemented, vehicles with BTSI experienced about a 60% drop in UA
  - Operating mode changed from P-D or P-R shifts to end-of-trip parking maneuvers in D or R

## ▶ Brake Throttle Override (BTO)

- Reduces throttle opening if the accelerator and brake pedals are depressed simultaneously under certain conditions
- Ensures that braking torque is greater than drive axle torque
- Software implementation, only possible in ETC vehicles
- Each company has different implementation strategy
  - Some depend on sequence of pedal application, vehicle speed, amount of brake application or fixed accelerator position to trigger override
  - Not a solution for all UA

# Defects Investigation Recommendations

- ▶ Are there practical ways to improve NHTSA's ability to find defects that may be based in electronic systems, particularly rare events where physical evidence is not apparent?