

CONDITION SURVEY OF SOIL-CEMENT ROADS

By W. H. MILLS, JR .

Last year the Subcommittee presented in a series of six tables¹ the pertinent data concerning the construction and condition after a period of service of 68 soil-cement projects in 23 States, which comprised practically all of this type of work in place at that time.

A more detailed analysis of the condition data has since been made and is presented here in order to complete the survey. For ready reference the tables, included in Figures 1 to 6 are reproduced.

The conditions of the projects were classified as: excellent, good, fair, poor and very poor.

In order to arrive at overall ratings for the projects, failed areas were assigned a value of 80 per cent, areas of deep ravel or softening to depths of ¾ in. to 2½ in. 15 per cent and areas of very thin ravel or surface scale 5 per cent. For instance; if a project contains 1 per cent failed area, 10 per cent deep ravel and 20 per cent surface scale the overall rating would be:

$$0.01 \times 80\% + 0.10 \times 15\% + 0.20 \times 5\% = 3.3\%$$

This would place the project in the classification "good" on the following scale:

Class	Overall rating, %
Excellent	Less than 1
Good 1 to 5
Fair 5 to 15
Poor 15 to 30
Very poor Over 30

On this basis the soil-cement bases of 64 projects were classified as follows: excellent 44, good 17, fair 3. Information for proper rating was lacking on four projects, and none was rated poor.

¹ Report of Subcommittee on Use of Portland Cement in Soil Stabilization, *Proceedings*, Highway Research Board, Vol 20, p 812

SUPPLEMENTARY DISCUSSION OF DATA

FIGURES 1, 2, 3

Age The projects in service vary in age from 1 to 7 years. Four projects in South Carolina are more than 5 years old and one project in Texas is over 7 years old. It should be remembered that projects less than one year old were not included as the committee felt that the service records on such projects would not be significant.

Soil Information is presented on the soils which were mixed with cement and on the subgrade soils. The data show that soils of almost every conceivable type have been used. In general, A-2 and 3 soils predominate but many projects are reported where A-4, 6 and 7 soils were used. The cement contents likewise vary greatly. The minimum cement content reported was on a project in South Carolina where 3 per cent by weight was used with a soil having 38 per cent clay, 19 per cent coarse sand and a plasticity index of 14. The maximum cement content of 14.5 per cent is reported on a project in Illinois where the soil has 34 per cent clay, no coarse sand and a plasticity index of 16. There are no definite relations between any of the soil tests and the cement contents but in general the cement content is increased with increases in the percentage of clay. The cement content for the projects was determined usually by laboratory tests designed to show differences not only in clay content, plasticity index, etc, but also differences due to organic matter. In most cases, the Tentative Standard Procedures of the A S T M. were followed. Seven to 7.9 per cent cement by volume is reported on 8.7 per cent of the projects, 8 to 8.9 per cent on 38 per cent of the projects, 9 to 9.9 per cent on 25 per cent of the projects, 10 to 10.9 per cent on 39 per cent of the projects. In most cases the quantity was

varied within the limits of a project due to differences in the soil and the foregoing figures in many instances include two or more percentages for the same project.

In general, the subgrade soils were of the same type as the material stabilized but in a few instances selected soils were used for the base course.

FIGURE 4

Climatic Conditions It is difficult to present any summary of these data because of great variations encountered in different sections of the country. The maximum annual rainfall reported was 60 in. and the minimum was 5.8 in. Nine projects are reported in areas having less than 20 in. annual rainfall and 32 where the rainfall is more than 40 in. Some rainfall is reported on practically all projects during construction. It is a coincidence that the project showing the least annual rainfall had the most rainfall during construction.

Snowfall ranged from a maximum of 72 in. on the upper peninsula in Michigan to a minimum of zero for projects in California and Georgia. Twenty-three projects had more than 10 in. of snowfall.

The minimum temperature reported was a low of -30° F. in New York. A project in Michigan was subjected to the most freezing as it was reported that the thermometer was below freezing for 159 days per year at this location. Alternations of freezing-thawing are probably more severe than continuous freezing but data on the number of alternations are not available.

Design: In general, design features of the projects varied almost as much as the climatic conditions. The widths varied from 9 to 30 ft. with shoulders from 1 to 10 ft. wide, ditches from 0.5 to 6 ft. deep and crown from $1\frac{1}{2}$ in. to 6 in. with most projects having 2 in. or less. The thicknesses are generally 6 in. compacted but a minimum thickness of 3 in. was re-

ported on one project and a maximum thickness of 14 in. on another.

Traffic The projects are for the most part subjected to relatively light traffic but on one project in Texas 6,800 vehicles per day is reported. The minimum reported is 43 vehicles per day. Forty projects have traffic densities below 500 and three projects have densities above 1,000. The traffic on the other projects is between 500 and 1,000 per day. Truck traffic is variable, a maximum of 684, 5-ton or heavier, trucks being reported on one project and none at other locations.

FIGURE 5

Equipment: The information shows that in general the same type of construction equipment has been used on all projects and that the mixed-in-place method has been followed on the majority of the projects. Fourteen projects have been constructed by traveling mixing plants and, of course, use of this equipment resulted in great differences in procedures. It is impossible to describe in this report the methods of handling the various pieces of equipment but this factor probably contributed more towards the efficiency of construction than the use of any particular apparatus.

Pulverizing Pulverization of the soil prior to the application of cement has caused considerable concern and the data show that in the majority of instances pulverization to at least 80 per cent passing the No. 4 screen was secured.

Spreading Cement: The hand method of applying cement was used generally but mechanical spreaders were used on 17 projects.

Compacting and Finishing All of the projects except some of the very old ones were compacted with a sheep'sfoot roller. Finishing operations and the rolling of the top surface are of great importance and generally the final rolling of the top of the surface was performed with a three-wheel steel roller. Some States re-

port the use of a roller with pneumatic tires for this operation and in a great many instances $\frac{1}{2}$ in to $\frac{1}{2}$ in of the top mulch was bladed off and wasted for the final finishing operation. In several instances softening of the top $\frac{1}{2}$ in. to 1 in. is reported where the final finishing was not satisfactory.

Protective Cover. Most of the bases were protected from evaporation losses for seven days following the final finishing operation. The use of wet earth is most common and was reported on 23.5 per cent of the projects. Wet straw and sawdust were used on 14.5 per cent of the projects, sprinkling for 2 or 3 days on 4.3 per cent and covering with waterproof paper on 1.4 per cent. Moist burlap or cotton mats were used on 4.4 per cent of the projects. Applications of tar prime are reported on 8.7 per cent, asphalt emulsions on 1.4 per cent and cut-back asphalts on 2.9 per cent. Three States report that no protection was used and no protective cover is reported for 26.1 per cent of all projects. At the completion of the curing period many of the projects were opened to traffic before the surface course was applied. This period varies from 0 to 425 days but in the majority of instances, the surfacing was applied before the base was 60 days old.

Prime: Tar was used as the priming

material in the majority of cases and 47.8 per cent of the projects are reported as primed with tar. In general, the quantity varied from 0.2 to 0.3 gal. per sq. yd. Cut-back asphalts were used on 30.4 per cent of the projects and asphalt emulsions were used on 4.3 per cent.

FIGURE 6

Condition The most frequent defect reported is that of scaling of the wearing surface which is frequently accompanied by slight softening of the top surface of the base; 43.5 per cent of the projects contain this defect. Areas in which there was deeper scaling or softening for depths of $\frac{3}{4}$ in. to $2\frac{1}{2}$ in. of the soil-cement base are reported on 27.5 per cent of the projects. Areas of actual failures of the soil-cement base are few in number and extent. No project was reported with more than 9.5 per cent of the total area as failures but some failures are reported on 27.5 per cent of all of the projects. Among different causes of failures are listed: (1) low cement content; (2) inadequate subgrade drainage and support; (3) unsatisfactory compaction due both to inadequate moisture control and poor subgrade support, (4) excessive mixing time after the application of the cement and water.

MATERIALS DATA ON SOIL-CEMENT PROJECTS

JUNIMBA	STATE & COUNTY	OFFICIAL DESIGNATION	LENGTH OF PROJECT MILES	AGE OF PROJECT YEARS	PI	SOIL DATA FOR SOIL PROCESSED			CEMENT CONTENT DATA			DATA ON SOIL-CEMENT MIXTURE			TYPE OF SOIL IN SUBGRADE
						% RETAINED ON SIEVE NO.	COARSE SAND	FINE	CLAY %	VOLUME %	WEIGHT %	LABORATORY #/CU FT.	FIELD #/CU FT.	FIELD %	
MA-1	ARK - WOODRUFF CO.	1085 N-153	1.877	1.25	16	32	32	32	12	11.3	103	103	103	13.0	A-1
MA-2	ARK - BRIDGESPORT CO.	1076 N-177	2.745	1.50	0	20	20	20	10	10.2	102	102	102	12.0	A-1
MA-1	ARK - GOODRICH CO.	N-664 R-6	0.5	0.5	0	14	14	14	10	10.2	102	102	102	12.0	A-1
MA-1	ARK - SHERIDAN CO.	N-315 T-8	3.00	2.5	0	22	22	22	10	9.2	111	111	111	11.6	A-1
CA-1	CA - CONTRASTION CO.	N-CC-106C	3.35	1.75	0	30	30	30	6	11.0	106	106	106	11.6	A-1
CA-2	CA - KERN CO.	N-315 T-8	3.00	2.5	0	22	22	22	10	9.2	111	111	111	11.6	A-1
CA-3	CA - KERN CO.	N-315 T-8	3.00	2.5	0	22	22	22	10	9.2	111	111	111	11.6	A-1
CA-4	CA - KERN CO.	N-315 T-8	3.00	2.5	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-1	OK - CLARK CO.	1502A	2.33	1.33	1	51	51	51	10	10.4	104	104	104	11.6	A-1
OK-2	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-3	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-4	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-5	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-6	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-7	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-8	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-9	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-10	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-11	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-12	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-13	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-14	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-15	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-16	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-17	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-18	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-19	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-20	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-21	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-22	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-23	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-24	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-25	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-26	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-27	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-28	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-29	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-30	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-31	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-32	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-33	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-34	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-35	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-36	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-37	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-38	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-39	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-40	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-41	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-42	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-43	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-44	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-45	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-46	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-47	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-48	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-49	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-50	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-51	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-52	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-53	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-54	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-55	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-56	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-57	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-58	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-59	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-60	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-61	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-62	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-63	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-64	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-65	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-66	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-67	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-68	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-69	OK - DEWELL CO.	1517	11.332	2.25	0	22	22	22	10	9.2	111	111	111	11.6	A-1
OK-70	OK - DEWELL CO.	1517	11.332	2.25	0	22	22</								

CONDITION OF SOIL-CEMENT AND BITUMINOUS COVER									
NUMBER	PERCENT OF TOTAL AREA OF SOIL-CEMENT WITH			FINAL OVERALL RATING %	FINAL OVERALL RATING	BITUMINOUS COVER THICKNESS CONDITION	NOTES ON SOIL CEMENT AND BITUMINOUS COVER DEFECTS		
	COMPLETE LOSS	DEEP RAVEL 1/4" - 2 1/2"	THIN RAVEL 0" - 1/4"				TOTAL	LOW CEMENT CONTENTS	INADEQUATE CONTROL OF SURFACE CONSTRUCTION
1A-1	5	50	2 1/2	19	17	GOOD TO FAIR			LOW CEMENT CONTENTS
1A-2	0	100	0	100	15 D	POOR			INADEQUATE CONTROL OF SURFACE CONSTRUCTION
1A-3	0	0	10	10	0	GOOD			SUBSINKING UNDER TRUCK TIRES SLIPS ON ICE
1A-4	0	0	50	50	0	EXCELLENT			SLIPPING UNDER SURFACE TREATMENT - ALSO CRACKING
1A-5	0	0	0	0	0	EXCELLENT			
1A-6	0	0	0	0	0	EXCELLENT			
1A-7	0	0	0	0	0	EXCELLENT			
1A-8	0	0	0	0	0	EXCELLENT			
1A-9	0	0	0	0	0	EXCELLENT			
1A-10	0	0	0	0	0	EXCELLENT			
1A-11	0	0	0	0	0	EXCELLENT			
1A-12	0	0	0	0	0	EXCELLENT			
1A-13	0	0	0	0	0	EXCELLENT			
1A-14	0	0	0	0	0	EXCELLENT			
1A-15	0	0	0	0	0	EXCELLENT			
1A-16	0	0	0	0	0	EXCELLENT			
1A-17	0	0	0	0	0	EXCELLENT			
1A-18	0	0	0	0	0	EXCELLENT			
1A-19	0	0	0	0	0	EXCELLENT			
1A-20	0	0	0	0	0	EXCELLENT			
1A-21	0	0	0	0	0	EXCELLENT			
1A-22	0	0	0	0	0	EXCELLENT			
1A-23	0	0	0	0	0	EXCELLENT			
1A-24	0	0	0	0	0	EXCELLENT			
1A-25	0	0	0	0	0	EXCELLENT			
1A-26	0	0	0	0	0	EXCELLENT			
1A-27	0	0	0	0	0	EXCELLENT			
1A-28	0	0	0	0	0	EXCELLENT			
1A-29	0	0	0	0	0	EXCELLENT			
1A-30	0	0	0	0	0	EXCELLENT			
1A-31	0	0	0	0	0	EXCELLENT			
1A-32	0	0	0	0	0	EXCELLENT			
1A-33	0	0	0	0	0	EXCELLENT			
1A-34	0	0	0	0	0	EXCELLENT			
1A-35	0	0	0	0	0	EXCELLENT			
1A-36	0	0	0	0	0	EXCELLENT			
1A-37	0	0	0	0	0	EXCELLENT			
1A-38	0	0	0	0	0	EXCELLENT			
1A-39	0	0	0	0	0	EXCELLENT			
1A-40	0	0	0	0	0	EXCELLENT			
1A-41	0	0	0	0	0	EXCELLENT			
1A-42	0	0	0	0	0	EXCELLENT			
1A-43	0	0	0	0	0	EXCELLENT			
1A-44	0	0	0	0	0	EXCELLENT			
1A-45	0	0	0	0	0	EXCELLENT			
1A-46	0	0	0	0	0	EXCELLENT			
1A-47	0	0	0	0	0	EXCELLENT			
1A-48	0	0	0	0	0	EXCELLENT			
1A-49	0	0	0	0	0	EXCELLENT			
1A-50	0	0	0	0	0	EXCELLENT			
1A-51	0	0	0	0	0	EXCELLENT			
1A-52	0	0	0	0	0	EXCELLENT			
1A-53	0	0	0	0	0	EXCELLENT			
1A-54	0	0	0	0	0	EXCELLENT			
1A-55	0	0	0	0	0	EXCELLENT			
1A-56	0	0	0	0	0	EXCELLENT			
1A-57	0	0	0	0	0	EXCELLENT			
1A-58	0	0	0	0	0	EXCELLENT			
1A-59	0	0	0	0	0	EXCELLENT			
1A-60	0	0	0	0	0	EXCELLENT			
1A-61	0	0	0	0	0	EXCELLENT			
1A-62	0	0	0	0	0	EXCELLENT			
1A-63	0	0	0	0	0	EXCELLENT			
1A-64	0	0	0	0	0	EXCELLENT			
1A-65	0	0	0	0	0	EXCELLENT			
1A-66	0	0	0	0	0	EXCELLENT			
1A-67	0	0	0	0	0	EXCELLENT			
1A-68	0	0	0	0	0	EXCELLENT			
1A-69	0	0	0	0	0	EXCELLENT			
1A-70	0	0	0	0	0	EXCELLENT			
1A-71	0	0	0	0	0	EXCELLENT			
1A-72	0	0	0	0	0	EXCELLENT			
1A-73	0	0	0	0	0	EXCELLENT			
1A-74	0	0	0	0	0	EXCELLENT			
1A-75	0	0	0	0	0	EXCELLENT			
1A-76	0	0	0	0	0	EXCELLENT			
1A-77	0	0	0	0	0	EXCELLENT			
1A-78	0	0	0	0	0	EXCELLENT			
1A-79	0	0	0	0	0	EXCELLENT			
1A-80	0	0	0	0	0	EXCELLENT			
1A-81	0	0	0	0	0	EXCELLENT			
1A-82	0	0	0	0	0	EXCELLENT			
1A-83	0	0	0	0	0	EXCELLENT			
1A-84	0	0	0	0	0	EXCELLENT			
1A-85	0	0	0	0	0	EXCELLENT			
1A-86	0	0	0	0	0	EXCELLENT			
1A-87	0	0	0	0	0	EXCELLENT			
1A-88	0	0	0	0	0	EXCELLENT			
1A-89	0	0	0	0	0	EXCELLENT			
1A-90	0	0	0	0	0	EXCELLENT			
1A-91	0	0	0	0	0	EXCELLENT			
1A-92	0	0	0	0	0	EXCELLENT			
1A-93	0	0	0	0	0	EXCELLENT			
1A-94	0	0	0	0	0	EXCELLENT			
1A-95	0	0	0	0	0	EXCELLENT			
1A-96	0	0	0	0	0	EXCELLENT			
1A-97	0	0	0	0	0	EXCELLENT			
1A-98	0	0	0	0	0	EXCELLENT			
1A-99	0	0	0	0	0	EXCELLENT			
1A-100	0	0	0	0	0	EXCELLENT			

-- NOT SHOWN

FIGURE 6