Chart 3 – Metal Culvert has Bedding Deficiencies