Chart 3 – Concrete Culvert has Bedding Deficiencies