Chart 2 – Metal Culvert Lacks Structural Capacity